Alexander Schleicher
GmbH & Co.
Segelflugzeugbau
D-6416 Poppenhausen

Subject:

Checking the parallel rocker (at the elevator actuator rod) in the fin. Exchange of this part and amendment to the Flight Manual.

Serial number applicability:

All ASK 23 ad ASK 23B serial no.s 23001 thru 23121. This TN no.8 is factory-standard as of serial no.23122.

Compliance:

Checking and - in case of damages found - exchanging the part prior to the next take-off. Otherwise the exchange has to be done until the next annual re-inspection, but not later than April 31, 1991.

Reason:

Two cases ASK 21 are reported where the parallel rocker at the automatic elevator connection broke. The same component is installed in the ASK 23 B.

Owing to improper action during rigging and/or de-rigging of the horizontal tailplane, sideways deformation or even breaking of the parallel rocker have been observed.

Another possible reason for such failure may be a foam cushion or other fixture in the glider trailer which fixes the fin from the top. If the necessary free moving of the elevator actuator rod which protrudes out of the fin, is not provided, the vibrations involved during the road transport can lead to sideways loads on the elevator actuator rod.

Action:

- Derig the horizontal tailplane and carefully check the parallel rocker for deformation and/or cracks (see Maintenance Manual page 14, Item no.16).
 If the parallel rocker is o.k., the glider may continue in
 - service until the next annual reinspection comes up, but no longer than April 31, 1991, at the latest. This does not mean that the "Daily Inspections" according to chapter IV.3.1 point 5 of the Flight Manual is no more effective!
- 2. If any damages are found on the parallel rocker, it has to be replaced by the new and stronger part <u>prior to the next</u> take-off.
- 2.1. For the exchange of the parallel rocker a hole 11 mm in diameter has to be drilled into the fin at the side of the bolthead in order to remove the M6 bolt. The hole needs not to be closed; only the edge of the drilled hole must be preserved afterwards.

Zuwiderhandlungen verptlichten zu Schadenersatz. Alle Rechte für den Fall der Patenterteilung oder Gebrauchsmuster-Einfragung varbehalten

| | | | I |
|-------------------------------------|---|------------------------------------|---|
| in zu Schadener. | der Patenterteilung | jung varbehalten." | |
| ndlungen verptlichten zu Schadener· | Rechte für den Fall der Patenterteilung | auchsmuster-Eintragung varbehalten | |

tergabe sowie Vervielfältigung dieser Unter- Zuwiderhandlungen v. Verwertung und Mitteilung ihres Inhalts nicht satz Alle Rechte für d attet, soweil nicht ausdrücklich zugestanden oder Gebrauchsmuste SHEET:

2 of 2

Technical Note
No. 8

Alexander Schleicher
GmbH & Co.
Segelflugzeugbau
D-6416 Poppenhausen

- 3. In the Flight Manual the pages 2a, 33, 34 and 35 must be exchanged for new pages with same page no. and date "Nov.26, 1990" and the revision entry "TN no.8".
- 3.1. The exchange of the pages has to be entered in the "Index of Corrections" (Page 1+2).
- 3.2. The instructions given in the new manual pages for rigging and derigging as well as for the trailer have to be carefully regarded.

Material & drawings:

Parallel rocker 99.000.4940 with modification status 1, dated 20.11.90.

Weight & Balance: Negligible.

Notes:

1. The Action can be done by a competent person. The exchange of the manual pages can be done by the owner of the glider himself.

The accomplishment of this mod must be certified by a licensed aviation inspector in the glider's inspection documents, the log-book, and in the Flight Manual.

2. The new parallel rocker according to drawing 99.000.4940 as well as the new manual pages are available from the manufacturer or his representative in the respective country.

Poppenhausen, November 26, 1990

ALEXANDER SCHLEICHER GmbH & Co.

(Lutz-W.Juntow)

The German original of this Technical Note has been approved by the LBA under the date of Dec.4,1990 (signature: Skov). The translation into Englisch has been done by best knowledge and judgement; in any case of doubt the German original is controlling.