Page 1 of 2 ASW 22 / B / BL Technical Note No. 16 **ASH 25 ASH 25 E** 

Technical Note No. 20 Technical Note No. 28

Alexander Schleicher GmbH & Co. Segelflugzeugbau D - 36163 Poppenhausen

Replacing a lever of the flap control system in the fuselage Subject:

Affected: **ASW 22** Type Certificate LBA 351 Series ASW 22 / 22 B / 22 BL

> ASH 25 Type Certificate LBA 364

ASH 25 E Type Certificate LBA 858 (with engine Rotax 275)

not affected: ASW 22 M, ASW 22 BLE (all series) and ASH 25 M / Mi

Classification: Major change

**Urgency:** Check until April 30, 2008. If a damaged lever is diagnosed, it has to be replaced imme-

diately. In any case, replacement has to take place before the next annual C. of A. in-

spection.

Reason: In an ASH 25 a partially broken lever of the flap control system was found in the fuselage.

On a few further sailplanes, gaps between the bearing flange and the lever plate were diagnosed indicating a bent lever. Black borders around the rivet heads also indicate dam-

age of the lever.

Fig. 1: Position of the flap lever behind the rear cross tube.




Fig. 2



Gap between bearing flange and lever plate

Action:

If a damaged lever is diagnosed during the check, which has to be made until April 30, 2008, the lever has to be changed immediately for the stronger new one (AS Part-No. 250.45.0070).

To change the lever, both U-shaped crossbeams must be unfastened. The complete substruction of the old lever has to be mounted on the new one. New secure nuts have to be used.

Page
2 of 2

ASW 22 / B / BL Technical Note No. 16
ASH 25 Technical Note No. 20
ASH 25 E Technical Note No. 28
D - 363

Alexander Schleicher GmbH & Co. Segelflugzeugbau D - 36163 Poppenhausen

Material and

drawings: Umlenkhebel I "TM 20" f. WK-St. AS Part-No. 250.45.0070

Weight (Mass)

and Balance: negligible

**Notes:** Structural action must only be done by the manufacturer of the sailplane (A. Schleicher)

or a repair station approved for such work.

All action has to be documented by an inspector authorised for such work in the sail-plane's log book, Flight and/or Maintenance Manual and the records of inspections.

i.A.

Poppenhausen, March 07, 2008

Alexander Schleicher GmbH & Co.

(M. Münch)

The German Original has been approved by the EASA on **March 18**, **2008** under the EASA project number **EASA.A.C.04999**.

The translation into English has been done by best knowledge and judgement; in any case of doubt the German original is controlling.