

Airworthiness Directive 97-009

Luftfahrt-Bundesamt

Airworthiness Directive Section Lilienthalplatz 6 38108 Braunschweig Federal Republic of Germany

Schleicher

Effective Date: January 30, 1997

Affected:

Kind of aeronautical product:

Manufacturer:

Powered Sailplane

Schleicher, Poppenhausen, Germany

Type: Models affected: ASH 26 E

Serial numbers affected:

ASH 26 E

German Type Certificate No.:

all 883

Subject:

Engine, engine internal air cooling

Reason:

Performance loss in the case of some few engine units has shown that the fan performance of the engine internal air cooling may be adersely affected under certain conditions. If a temperature alarm by the ILEC-engine control unit is not regarded or is not given because of a defective sensor (no temperature indication) as a possible consequence the engine will be operated at higher temperatures than possible and may become damaged gardually. For this reason there must be at once a better check of the cooling air temperature. In order to solve this problem generally the fan of the engine internal air cooling must be exchanged for an upgraded unit.

Action:

- a) Checking the cooling air temperature in flight and inspection of further engine unit parts.
- b) Improvement and change of the fan of the engine internal air cooling and exchange of the temperature sensor of the internal air cooling.

Compliance:

- a) Before the next flight.
- b) At the earliest possible date; immediately in case of increased cooling air temperature but at latest during the next annual inspection.

Technical publication of the manufacturer:

Schleicher ASH 26 E Technical Note No. 1 dated November 12, 1996 which becomes herewith part of this AD and must be obtained from Messrs.:

Alexander Schleicher Segelflugzeugbau

D-36163 Poppenhausen Federal Republik of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.

Enquiries regarding this Airworthiness Directive should be referred to Mr. Claf Schneider, Airworthiness Directive Section at the above address, fax-no. 0049 531/2355-254. Please note, that in case of any difficulty, reference should be made to the German issue!