

Sheet 2 of 2		ASH 26 E Technical Note No. 8	Alexander Schleicher GmbH & Co. Segelflugzeugbau D - 36163	
Action:	a) If the inspection shows that an exchange of the exhaust damper becomes necessary, the customer must obtain a new exhaust damper from Schleicher GmbH. The part must be installed in accordance with the instructions supplied with it.			
	b) If the exhaust damper is marked by an 'X, it must be removed and returned (together with the CFRP fairing) to Schleicher GmbH for inspection - at the latest on expiry of the deadline stated in para "Compliance under b)".			
	but wi	The following manual pages must be exchanged for new pages with the same page no., but with the revision entry & date "TN 8 / 23.08.99". The exchange of the pages in the Manuals must be documented on the respective page "Record of Revisions".		
	FM p.:	2.4 , 2.11, 4.9 , 4.16 , 5.8 , 7.2 , 7.23 , 7.24 , 7	.25,7.31	
	MM p. Legen	 2.12, 2.14, 2.18, 2.24, 2.25, 2.30, 2.31, 2.32, 7.9, 9.8, 10.3, 12.4, 12.8. d: Flight Manual pages = FM p. // Maintenance Manu 		
	5			
Material and Drawings:		est damper according to drawing 800.65.0001 by Schlust damper fairing according to drawing 800.65.0011/0		
Mass & C.G.:	After the exhaust damper has been removed it must be weighed together with its fairing. The difference in mass compared to the new exhaust damper (including its fairing), must be used for correcting the calculation of the empty mass c.g. which was noted in the previous valid Weight & Balance Form, and where necessary the minimum cockpit load must be corrected. For this correcting calculation a value of 1430 mm as of datum can be assumed as the lever arm of the exhaust damper.			
Notes:	The ir scope Mainte Exhau The ir be do license	 Exhaust damper <u>without</u> 'X' and less than 40 hours: The inspection of the CFRP fairing must be made by a competent person within the scope of a pre-flight inspection and must be certified each time in the logbook in the block Maintenance Works. Exhaust damper <u>without</u> 'X' and more than 40 hours: The inspection of the front side of the exhaust damper for tempering coloration can only be done by means of an endoscope. This inspection can be done by an appropriately licensed inspector or by a technical aviation service station holding an appropriate license, it must be certified in the sailplane's log. 		
	b) Exhaust damper version with an 'X':			
	The inspection of this version can only be done by Schleicher GmbH. After the exchange or re-installation of the inspected exhaust damper the corresponding			
	entry in the inspection documents must be made.		ust damper the corresponding	
	manuf	exchange of the exhaust damper system must o facturer Alexander Schleicher or by a technical aviat priate license.		
	himse docun "Index	xchange of the pages in the Manuals can be done lf. The accomplishment of the exchange of the pa nented on the respective page "Record of Revisions" of Effective Pages" (Section 0, under 0.2) the date anged to "23.08.99" by hand.	ages in the Manuals must be " (Section 0, under 0.1). In the	
Poppenhausen, August 23, 1999		, 1999 Al	exander Schleicher GmbH & Co.	
		i.A.	(Martin Heide)	
The German original of this Technical Note has been approved by the LBA under the date of August 31, 1999 (signature: KOPP). The translation into English has been done by best knowledge and judgement; in any case of doubt the German original is controlling.				