		ē	ontrollir	afis c	9 1 1 1	doubt the German original is controlling.	ot the	헏
English has been done by best knowledge	best	γ	done	been	has	English	on into	9
L.W. Jur	Ž							

Action: Subject: Reason: Compliance: Affecting: 앜 N 1. This is checked by connecting the brakes individually and marking the point on the operating lever gate in the cockpit at which the linkage's dead center occurs. Both dead points should be within 5 mm (0.2 in) ing of the airbrakes. Each airbrake has its own toggle in the wing. For this reason it must be checked that both airbrakes lock simultaneously and securely. It is important to check in regular intervals the lock-As required All ASK 21 serial no.s. Re-adjusting the airbrakes If you observe that the airbrakes do not have an even over-center lock, the toggle over dead center must be If the airbrakes still do not have sufficient dead again as described under point 1.). 1 turn. Re-connect in the reverse order and check As shown in Fig.1 the short pushrod (1) is to be disconnected from the toggle crank (2); back off the lock-nut (3) and screw out the pushrod (1) by 1/2 to readjusted. This must be done with the airbrake push-rod disconnected from the HOTELLIER ball quick-disconof each other and, in the locked state, the individual brakes should still have 10 mm of free movement of the front lever forwards in the gate. nect. Maintenance Instruction A force, peel a little off the Alexander Schleicher Segelflugzeugbau D - 6416 Poppenhausen

SHEET:

New safety nut NM 6, DIN 980-6, if needed. block (4). Using a punch carefully remove some layers from the stop block (4); then again readjust the airbrakes as described under points 1.) and 2.). ALEXANDER SCHLEICHER stop

Poppenhausen, March 23, 1987

Material:

The translation any case of do ge and judgement; in

