
Technical NoteNo. 41Technical NoteNo. 15

Subject: Applicability:	Cracks in the bonding of the wing root rib ASK 21; Type-Certificate EASA.A.221 Models ASK 21 and ASK 21 Mi ; all serial numbers	
Classification:	Major Change	
Urgency:	Action 1 "Inspection for Cracks" until 31.12.2019 at the latest, afterwards annual Actions 2 and 3 if necessary	
Reason:	Inspection for cracks in the bonding of spar and wing shell (in the area of the root rib), resp. root rib and repair of the bonding, if necessary	
Action:	1. Inspection for Cracks	
	Cracks might occur at the following locations in the bon	ding joints:
	<image/>	At the edge between root rib, spar and wing shell In the bonding joint between root rib and spar Photo example: Root rib ASK 21 B, left wing, spar fork. The accompanying illustration is also valid for the right wing (spar stub).

Further the bonding joints have to be checked for cracks also from the rear side (from inside the wing) - accessible via the openings resp. the throughputs of the control rods – by a mirror or a borescope.

2. Crack Assessment



White markings (delamination) in the structural parts (root rib, shell, spar) and debondings, found by ping testing of the bonding joints, indicate a bigger damage, causing an appropriate bigger repair according TN 02-2005.

The same applies for cracks, which continue deeper than the stated above 10 mm (0.4 in) or even until the rear side of the bonding joint of the root rib. These are signs of structural overloads and are not comparable to the cracks described in this technical note.

3. Repair

Repair Scheme 1

for cracks in the edges



Anneal the repair after finishing according to repair manual min. 12h at 55°C (131°F).


ASK 21 ASK 21 Mi

Technical Note Technical Note

No. 41 No. 15 Alexander Schleicher GmbH & Co. Segelflugzeugbau D - 36163 Poppenhausen

Repair Scheme 2

Cracks also in the vertical bonding joint



The cracked bonding cement has to be removed resp. v-shaped milled to the crack root.

Warning!

The fibres of root rib, spar (especially the winding outside of the spar) or the wing shell must not be damaged.

Clean the area thoroughly (especially from oil or grease) and roughen the surface. Smooth the step from the root rib flange to the spar with a \sim 30° ramp of bonding cement and apply the following laminate scheme:

2 Plies 92140 diagonal

alternatively 2 Plies 92130 diagonal

The first ply is applied 40 mm (1.6 in) from the edge of the root rib onto the spar and 30mm (1.2 in) from the edge of the root rib onto the root rib.

The second ply is applied the same way, but 10 mm (0.4 in) shorter on each side (stepped). It is also possible to apply the shorter ply at first.

Finally apply peel ply.

Anneal the repair after finishing according to repair manual min. 12h at 55°C (131°F).

Repair Scheme 2a

Separation in the vertical bonding joint



Separations, **not** deeper than 10 mm (0.4 in), can be repaired as follows:

Inject resin with a syringe via a small drilling (< 1.5 mm / 0.06 in) near the end of the root rib into the separated area.

Warning!

The fibres of root rib, spar (especially the winding outside of the spar) or the wing shell must not be damaged.

Further repair as per **repair scheme 2**.

Anneal the repair after finishing according to repair manual min. 12h at 55°C (131°F).

Material and		
Drawings:	In case of a repair:	
	Glass fabric Interglas 92140 or 92130	
	Resin system L335 (H335 / H338 / H340) or L285 (H285 / H286 / H287)	
	For the preparation of the bonding cement: 100 parts by weight resin required parts by weight hardener 20 parts by weight cotton flocks 10 parts by weight Aerosil	
Mass and		
Balance:	The change in mass and C. of G. position is negligible.	
Notes:	The structural measures must only be accomplished by the manufacturer Alexander Sch cher or by qualified staff according to applicable law (European Union Commission Regulation (EC) 1321/2014 Part M).	
	All actions have to be inspected as complex maintenance by certifying staff according to M.A.801 (EC 1321/2014) and have to be certified in the sailplane inspection documents and in the sailplane logbook.	
	In countries outside the scope of EC 1321/2014 the corresponding national rules shall apply.	
Poppenhausen, 04.02.2019		
	Alexander Schleicher GmbH & Co.	
	i.A. P. Addama (P. Anklam)	
This Technical Note bases on a change, which was approved by EASA under the major change approval EASA 10068550.		