


- Subject:** a) Replacement of the electric fuel pump  
b) Replacement of the flange for the fuel tank sensor
- Applicability:** **ASK 16**; Type-Certificate LBA 758; all serial numbers
- Classification:** Minor Change
- Urgency:** optional
- Reason:** The existing fuel pump and the existing flange for the fuel tank sensor are no longer available.
- Action:** Actions a) and b) can be done independently of each other.
- a)  
Replacement of the electric fuel pump Autoflux Speed up / Type Z 12 – 35 N8 by Pierburg 7.21440.51.0 or Pierburg 7.21440.53.0.
- b)  
Replacement of the flange for the fuel tank sensor VDO N05 801 434 by VDO N05 801 432.
- Material and Drawings:** See Action
- Mass and Balance:** The change in mass and C. of G. position is negligible.
- Notes:** The structural measures must only be accomplished by the manufacturer Alexander Schleicher or by qualified staff according to applicable law (European Union Commission Regulation (EC) 1321/2014 Part M).
- All actions have to be inspected as non-complex maintenance by certifying staff according to M.A.801 (EC 1321/2014) and have to be certified in the sailplane inspection documents and in the sailplane logbook.
- In countries outside the scope of EC 1321/2014 the corresponding national rules shall apply.

Poppenhausen, 17.01.2020

**Alexander Schleicher**  
GmbH & Co.

i.A.   
(P. Anklam)

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10068550.