Page

Action:

1 of 1

ASK 13 Technical Note

No. 22

Alexander Schleicher

GmbH & Co. Segelflugzeugbau D - 36163 Poppenhausen

Subject: Inspection of the control stick attachment in the rear cockpit

Applicability: ASK 13; all serial numbers

Urgency: optional, strongly recommended during each annual maintenance


Reason: During the winch launch of a glider of ASK 13 model the control stick in the rear seat came

loose despite tightened wing nut. The cause were deformed components, which prevented

correct clamping of the control stick.

 Inspect the welded bushings for deformation. They must not be deformed to such an extent that it is no longer possible to tighten the wing nut.

2) Inspect the slot in the tube. This must be at least 2 mm (0.08 in.).



3) With the control stick mounted, check that it is firmly seated.

Material and

Drawings: See Action

Mass and

Balance: No change in mass and C. of G. position.

Notes: When the control stick is disassembled, the wing nut must not be tightened to avoid defor-

mation of the components. The loose wing nut is secured against falling out by a split pin

in the screw.

The action has to be considered as a pilot-owner maintenance task regarding aviation law.

The respective regulations must be applied.

Poppenhausen, 15.06.2023

Alexander Schleicher

GmbH & Co.

i.A. P. Asklam)

This Technical Note bases on the initial type certification and is a service information only.