

Airworthiness Directive

---

78-303 Schleicher

Date of issue:

November 13, 1978

Affected sailplanes:

German Type Certificate No.308.

ASW 19, serial numbers 19001 through 19232.

German Type Certificate No.314.

ASW 20, serial numbers 20001 through 20113 except 20111.

Subject:

Handhole cover in fuselage.

Reason:

Possible jamming of aileron and flap control by the handhole cover pulled into the fuselage.

Action and compliance:

1. Tape the handhole cover in the fuselage carefully before every flight after effective date of this AD until accomplishment of action No.2.
2. Unless already accomplished proceed in accordance with technical note during the next annual inspection but not later than March 31, 1979.

Technical Note of the manufacturer:

1. Schleicher ASW 19 Technical Note No.7 of September 11, 1978

2. Schleicher ASW 20 Technical Note No.4 of September 11, 1978

which become herewith part of this AD and may be obtained from Messrs. Alexander Schleicher, Segelflugzeugbau, D-6416 Poppenhausen, Western Germany.

Accomplishment and log book entry:

Action to be accomplished by a skilled person and to be entered in the sailplane's log by a licensed inspector.