

Airworthiness Directive  
=====

84-21 Schleicher

Date of issue:  
March 6, 1984

Affected sailplane:  
German Type Certificate No. 308  
Schleicher ASW 19 und ASW 19B  
serial number 19001 until 19399.

Subject:  
Service life of glider

Reason:  
Possibility to extend the approved service time  
to 6000 hours.

Action and compliance:  
Action to be accomplished in accordance with technical  
note before reaching 3000 service hours, before the next  
annual inspection but not later than December 31, 1984.

Technical publication of the manufacturer:  
Schleicher Technical Note No. 16 of February 1, 1984,  
which becomes herewith part of this AD and may be  
obtained from Messrs. Alexander Schleicher, Segelflugzeugbau,  
D-6416 Poppenhausen, Federal Republic of Germany.

Accomplishment and log book entry:  
Action to be accomplished by an approved service station  
and entered in the glider's log by a licensed inspector.