

Airworthiness Directive

77-294 Schleicher

Date of issue:
November 14, 1977

Affected sailplane:

ASW 20 (German type certificate
no. 314).
Serial numbers 20001 through 20018
and 20020 through 20024.

Subject:

Forward tow hook attachment point.

Reason:

Reinforcement of tow hook installation.

Action and compliance:

On the occasion of the next annual inspection proceed in accordance with Technical Note.

Technical Note of the manufacturer:

Schleicher ASW 20 Technical Note No. 1 of October 18, 1977, which becomes herewith part of this AD and is available from Messrs. Alexander Schleicher Segelflugzeugbau, D-6416 Poppenhausen, Western Germany.

Accomplishment and log book entry:

Action to be accomplished by a skilled person and to be entered in the sailplane's log by a licensed inspector.