

Airworthiness Directive

84-115 Schleicher

Date of issue:
July 16, 1984

Affected sailplane:

German Type Certificate No. 308
ASW 19 and ASW 19B
Serial number 19001 until 19405;

German Type Certificate No. 314
ASW 20 and ASW 20L
Serial number 20001 until 20611
ASW 20B
Serial number 20620 until 20626.

Subject:
Tow release

Reason:
Mal-function due to possible wrong assembly
of the cable guide fitting.

Action and compliance:
Action to be accomplished in accordance with
Technical Note prior to the next flight.

Technical publications of the manufacturer:
Schleicher ASW 19 and ASW 19B, Technical Note No. 18
and ASW 20, 20L and 20B No. 21 of July 3, 1984,
which becomes herewith part of this AD and may be
obtained from Messrs. Alexander Schleicher,
Segelflugzeugbau D-6416 Poppenhausen, Federal Republic
of Germany.

Accomplishment and log book entry:
Action to be accomplished by a skilled person and to be
entered in the sailplane's log.