

Airworthiness Directive

86-236 Schleicher

Date of issue:

November 18, 1986

Affected sailplane:

German Type Certificate No. 339
Schleicher ASK 21
serial numbers 21001 until 21312

Subject:

Directional control-bracket assembly

Reason:

Possible cracks in the bracket assembly

Action and compliance:

Action to be accomplished in accordance with Technical Note immediately after the effective date of this AD.

Technical publication of the manufacturer:

Alexander Schleicher ASK 21 Technical Note No. 19 of October 22, 1986, which becomes herewith part of this AD and may be obtained from Messrs. Alexander Schleicher, Segelflugzeugbau, D-6416 Poppenhausen, Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by a skilled person and to be checked and entered in the sailplane's log by a licensed inspector.