

AIRWORTHINESS DIRECTIVE

91-112 Schleicher

Date of issue:

June 19, 1991

Affected sailplane:

German Type Certificate No. 339

ASK 21

Serial-numbers 21 001 through 21 495 inclusive

Subject:

Revision of the Flight Manual (FM)

Reason:

Descriptions of relevant flight conditions for spins themselves, spin entry and of recovery from spins.

Action and compliance:

Exchange of revised FM-pages in accordance with Technical Note No. 23 until next annual inspection.

Technical publication of the manufacturer:

ASK 21 Technical Note No. 23 of January 29, 1991

which becomes herewith part of this AD and may be obtained from Messrs.

Alexander Schleicher GmbH & Co.

Segelflugzeugbau

D-6416 Poppenhausen

Federal Republic of Germany

Accomplishment and log book entry:

Action to be accomplished by the owner and to be checked and entered in the sailplane's log by a licensed inspector.