

Subject: Amendment to the Manuals in English language.

Affected gliders: All ASK 21s.

Compliance: Immediately on receipt of documents.

Reason: It has been found that one placard was included in German language instead of the English language.

Action:

1. In the English version of the Manuals, the Maintenance Manual page 56 has to be exchanged against page 56a.
In the FAA-approved US-edition of the Manuals, the Flight Manual pages 2 (dated Dec. 20, 1983) and 21 (dated March 9, 1983) have to be exchanged against pages 2 + 21 (dated May 16, 1984); in the "Instructions For Continued Airworthiness" pages 2 (dated Dec. 20, 1983) and 59 (dated March 9, 1983) must be exchanged against pages 2 + 59 (dated May 16, 1984).
2. A new placard in English language must be fitted in the front and rear cockpit in full view of the pilot.

Material: Will be supplied by Schleicher.

Weight & balance: Not applicable.

Poppenhausen, May 16, 1984

ALEXANDER SCHLEICHER
GmbH & Co.

Rudolf Kaiser
(Rudolf Kaiser)



grüß
2/8. Mai 1984