Page 1 of 1 ASW 28 / ASW 28-18 ASW 28-18E

TN Nr. 1 TN Nr. 1 Alexander Schleicher
GmbH & Co.
Segelflugzeugbau
D - 36163 Poppenhausen

Subject: Relocation of aerotow hook to the fuselage nose

Applicability: ASW 28, ASW 28-18, type certificate: EASA.A.017 (former LBA TC Nr. 423)

ASW 28-18E, type certificate: EASA.A.034

Urgency: None, optional retrofit

By new assembling with front tow release in the fuselage tip

Reason: Adjustment of the ventilation intake, installation of the tow release attachment (bulkhead)

and of a bulkhead for the ventilation, and modification of the operating mechanics.

Installation of a tow release TOST E22 (Approval No. 11.402/9 NTS)

In case a release is already installed in front of the stick bulkhead, it is removed together

with its control system and the hole in the fuselage skin is closed.

Action: See material and drawings

Exchange the following manual pages:

	Flight Manual	Maintenance Manual
ASW 28	-	2.19, 4.4, 8.4, 10.7, 12.7
ASW 28-18	-	2.34, 4.4, 8.4, 10.7, 12.11
ASW 28-18E	5.3	2.34, 4.4, 8.4, 10.7, 10.8, 12.11

Material and

Drawings: for ASW 28, ASW 28-18:

280.11.0020 assembling of the front tow release

for ASW 28-18E:

288.11.0020 assembling of the front tow release with pitot

Mass and C.G.: It is necessary to re-determine the C.G data by weighing.

Notes: The retrofitting may only be accomplished by the manufacturer Alexander Schleicher

GmbH & Co. or by a technical aviation repair station holding an appropriate license. All actions must be examined in the glider logbook, Flight & Maintenance Manual, and in the glider inspection certificates. The accomplishment of the change of the manuals must be entered on the page "Record of Revisions" and in the "List of effective pages" in both

manuals.

Material and manual pages can be ordered by Messrs. Alexander Schleicher GmbH & Co., Tel. +49 (06658) 89-0, Fax +49 (06658) 89-40 or e-mail: sales@alexander-

schleicher.de

Poppenhausen, 12th of July, 2006

Alexander Schleicher

GmbH & Co.

i. A.

(Michael Greiner)

The German original has been approved by the EASA on the 18th of July, 2006 with change number EASA.A.C.04345. The translation into English has been done by the best knowledge and judgement; in any case of doubt the German original is controlling