

Alexander Schleicher
Segelflugzeugbau
Poppenhausen/Wasserk.

Modification No. 12
Glider Rhönlerche II
L - 164

Sheet 1
Nb of. Sheets 1

Installation of aileron mass - balance

Probably due to too loose cables aileron flutter occurred at lower than placard airspeed.

Description of modification:

After drawing L - 164.31 - S 2 an aileron mass balance weight has to be installed. The installation kit can be ordered from Fritz Brockmeier Sportflugzeugbau, 483 Gütersloh, Kahlertstr. 41.

Drawings to be corrected

Remarks

LBA - Check

ausgef. 11.10.67

All Seral No. of
Rhönlerche II are
concerned.