

Subject: Examination of the canopy lock

Effectivity: Glider K 8 , K 8 B , K 8 C


Accomplishment: To be made until 01.08.1980.

Instruction: The canopy lock has to be examined if the cam is at least 2 mm high.
 If not, take a file to make it deeper.
 Note the examination in the log book.

Material: --

Weight and

Balance: --



Poppenhausen, 12.05.1980

ALEXANDER SCHLEICHER
 Segelflugzeugbau
Rudolf Meiser
 (Rudolf Meiser)