

AIRWORTHINESS DIRECTIVE

91-144 Schleicher/JUBI

Date of issue:

31. JULI 1991

Affected sailplane

German Type Certificate No. 267  
AS-K13,  
Serial No. 13618 through 13686 inclusive  
and Serial No. 13689, all with addition "A. B."

Subject: Wing main fittings

Reason:

Possible non-observance of the tolerance on the backside of the main fitting-holes can lead to a light movement from the main fitting to the end spar.

Action and compliance:

Action to be accomplished in accordance with Service Bulletin No. 13 before next flight after the effective date of this AD, unless already accomplished.

Technical publication of the manufacturer:

AS-K13 Service Bulletin No. 13 of December 19th, 1990, which becomes herewith part of this AD and may be obtained from Messrs.

JUBI GMBH  
ROBERT-KRONFELD-STR. 2  
D-4811 OERLINGHAUSEN  
Federal Republik of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the sailplane's log by a licensed inspector.