

AIRWORTHINESS DIRECTIVE

89-121 Schleicher

Date of issue :
June 28, 1989

Affected powered glider:
German Type Certificate No. 684
ASK 14,
all powered gliders

Subject:
Fueltank

Reason:
Possible Failure of the Fueltank Transparence

Action:
Action to be accomplished in accordance with Technical Note

Compliance:
Action 1 of Technical Note:
Before the next flight
Action 2 of Technical Note:
Before the next annual inspection, but not later than
December 31, 1989

Technical publication of the manufacturer:
Alexander Schleicher, ASK 14 Technical Note No. 6
of May 6, 1989
which becomes herewith part of this AD and may be obtained from Messrs.
Alexander Schleicher GmbH & Co. Segelflugzeugbau,
D-6416 Poppenhausen, Wasserkuppe, Federal Republic of Germany

Accomplishment and log book entry:
Action to be accomplished by an approved service station.
The exchange of the fueltank can be accomplished only by the
manufacturer or a therefore approved service station.
The accomplishment of this AD must be certified by a licensed
inspector in the powered gliders inspection documents and in the
log-book.

Note:
For replacements use only original material of the manufacturer.