

AIRWORTHINESS DIRECTIVE

81-265 Schleicher

Date of issue:
January 21, 1982

Affected sailplanes and powered gliders:

German Type Certificate No. 272
ASW15 and ASW15B, including existing modifications into
powered gliders.

Subject:

1. Elevator actuator bellcrank
2. Operations Manual

Reason:

Possibility of fatigue failure of the bellcrank actuating
the elevator.

Action and compliance:

Proceed in accordance with instructions No. 1 to 5 of
Technical Note No. 21 until March 1, 1982 latest unless
already accomplished.

Technical publication of the manufacturer:

Schleicher ASW15, ASW15B Technical Note No. 21
of November 24, 1981 which becomes herewith part of
this AD and may be obtained from Messrs. Alexander
Schleicher Segelflugzeugbau, D-6416 Poppenhausen,
Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by an approved service station
and to be checked and entered in the sailplane's log by
a licensed inspector.