

Airworthiness Directive

=====

82-221 Schleicher

Date of issue:

October 25, 1982

Affected sailplanes and powered sailplanes:

German Type Certificate No. 272

ASW 15 and ASW 15B, including existing modifications into powered sailplanes.

Subject:

1. Elevator actuator bellcrank
2. Operation Manual

Reason:

Possible fatigue failure of the bellcrank actuating the elevator.

Action and compliance:

Proceed in accordance with the Technical Note.

Technical publication of the manufacturer:

Schleicher ASW 15, ASW 15B Technical Note No. 22 of November 1, 1982,

which becomes herewith part of this AD and may be obtained from Messrs. Alexander Schleicher, Segelflugzeugbau, D-6416 Poppenhausen, W. Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the sailplane's log by a licensed inspector.

Note:

After the accomplishment of part 2 and 3 of the Technical Note 22, this Airworthiness Directive replaces LTA 81-265 of January 21, 1982.