

AIRWORTHINESS DIRECTIVE

88-95 Schleicher

Date of issue:

25. April 1988

Affected sailplanes and powered sailplanes:

German Type Certificate No. 272

All ASW 15 and ASW 15B, including existing modifications into powered sailplanes.

Subject:

Wingspar

Reason:

In flight failure of the wing structure.

Action:

Action to be accomplished in accordance with Technical Note.

Compliance:

Action 1.1 through 1.3 of Technical Note: Before the next start.
All other Actions before 31. Dezember 1988.

Technical publication of the manufacturers:

Schleicher ASW 15 Technical Note No. 23 of April 21, 1988, which becomes herewith part of this AD and may be obtained from Messrs. Alexander Schleicher, Segelflugzeugbau, D-6416 Poppenhausen, Federal Republic of Germany.

Accomplishment and log book entry:

Action 1.1 through 4 to be accomplished by the manufacturer or an approved service station.

Action 5 may be accomplished by a skilled person.

All actions to be checked and entered in the planes log by a licensed inspector.