

Sheet : 1
Number of Sheets : 1

ASW 15
Technical Note
No. 14

Alexander Schleicher
Segelflugzeugbau
6416 Poppenhausen

Kind : Technological Improvement,
better maintenance

Subject : Fitting of all-flying-tail on elevator and fin.

Effectivity : ASW 15 - B from Serial No. 15 382

Accomplishment : None

Reason : The replacement of worn out metal pins of the
elevator was difficult, as the sandwich of the
elevators had to be opened.
This modification cares for an easier exchange of
the pins, because they are now installed in the
fitting of the fin.

Instructions : According to the drawings : 151.36.0025
151.35.0026
151.35.0027
151.35.0028
151.36.0029
151.36.0030
151.35.0031
151.35.1011
the parts are manufactured and installed according
drawing 151.35.8 36.

Material : See under " Instructions "

Weight and Balance : For this modification a weight and balance is
necessary.

Remarks : 1. Structural strength calculations have been made
for this modification. They are documented on
pages 3243 and the following of the ASW 15 - B
substantiation.
2. For repairs of the empennage and the rear
fuselage the modification according to this
TN can be made on all ASW 15 since Serial No.
15 001.

Drawings : The drawings listed above under " Instructions "
are new.
The following drawings are replaced by them :

151.35.0026	replaces	150/51 35.0003
151.35.0027	"	150/51 35.0007
151.35.0028	"	150/51 35.0008
151.36.0029	"	150/51 36.0009
151.36.0030	"	150/51 36.0010
151.35.1011	"	150/51 35.1010
151.35.8 36	"	150/51 34.Bl. 16

Poppenhausen, 3rd July, 1974

Alexander Schleicher
ALEXANDER SCHLEICHER
Segelflugzeugbau