

AIRWORTHINESS DIRECTIVE

89-81 Schleicher

Date of issue:

**16. AUG. 1989**

Affected powered glider:

German Type Certificate No. 758

ASK 16 and ASK 16B

all powered gliders

Subject:

Fuel tank

Reason:

Possible Failure of the Fuel tank Transparence

Action:

Action to be accomplished in accordance with Technical Note

Compliance:

Action 1 of Technical Note:

Before the next flight

Action 2 of Technical Note:

Before the next annual inspection, but not later than

December 31, 1989

Technical publication of the manufacturer:

Alexander Schleicher, ASK 16 Technical Note No. 10

of July 26, 1989

which becomes herewith part of this AD and may be obtained form Messrs.  
Alexander Schleicher GmbH & Co. Segelflugzeugbau,  
D-6416 Poppenhausen, Wasserkuppe, Federal Republic of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station.

The exchange of the fuel tank can be accomplished only by the  
manufacturer or a therefore approved service station.

The accomplishment of this AD must be certified by a licensed  
inspector in the powered gliders inspection documents and in the  
log-book.

Note:

For replacements use only original material of the manufacturer.