

Airworthiness Directive
=====

85-90 Schleicher

Date of issue:

April 12, 1985

Affected glider:

German Type Certificate No. 351

ASW 22

serial numbers 22002 until 22015,
22017 until 22019,
22021 and 22022,
22024 until 22027,
22031 and 22032,
22036 and 22037,
22039 and 22047.

Subject:

Trim spring

Reason:

Decrease of the spring tension due to unfavorable choice of material.

Action and compliance:

Action to be accomplished in accordance with Technical Note before the next annual inspection but not later than December 31, 1985.

Technical publication of the manufacturer:

Schleicher ASW 22, Technical Note No.2 of March 15, 1985, which becomes herewith part of this AD and may be obtained from Messrs. Alexander Schleicher, Segelflugzeugbau, D-6416 Poppenhausen, Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by a skilled person and to be checked and entered in the sailplane's log by a licensed inspector.