



Recommended Service
Bulletin
No. RSB-AE50R-005

Austro Engine GmbH
Rudolf-Diesel-Strasse 11
A-2700 Wiener Neustadt
Tel: +43 2622 23000
FAX: +43 2622 23000-2711

RECOMMENDED SERVICE BULLETIN

No. RSB-AE50R-005

1. BASIC INFORMATION

1.1. SUBJECT

Carburetor Retrofit

1.2. ENGINES AFFECTED

Type: AE50RAB

Serial numbers: all

1.3. REASON

This RSB ensures the usability of the new carburetor design in case of retrofit for the engine serial numbers defined under chapter 1.2.

1.4. TIME OF COMPLIANCE

Not applicable.


1.5. CONCURRENT DOCUMENTS / REFERENCES

None.

1.6. OTHER PUBLICATIONS AFFECTED

None.

First Issue Date			Rev. No.	Revision Date				Page
10	May	2010	---	---	---	---	1-3	

	<p style="text-align: center;">Recommended Service Bulletin No. RSB-AE50R-005</p>	<p>Austro Engine GmbH Rudolf-Diesel-Strasse 11 A-2700 Wiener Neustadt Tel: +43 2622 23000 FAX: +43 2622 23000-2711</p>
---	---	--

2. TECHNICAL DETAILS

2.1. ACCOMPLISHMENT / INSTRUCTIONS

In case of retrofit it is recommended to exchange the old with the new carburetor design. The new carburetor design with the part number R1B-31-100-000 Rev. 020 can be installed on the engines serial numbers defined under chapter 1.2.

2.2. ILLUSTRATIONS

None.

2.3. MASS (WEIGHT)

None.

2.4. APPROVAL STATEMENT

The technical information or instructions contained in this document relate to the Basic Type Design which has been approved by EASA and to the Design Change Report No. MDC-E1-093b which has been approved under the authority of DOA No. EASA.21J.399.

The technical content of this document has been approved under the authority of DOA No. EASA.21J.399.

3. PLANNING INFORMATION

3.1. MATERIAL & AVAILABILITY

Carburetor R1B-31-100-000 Rev.020

3.2. SPECIAL TOOLS

Not applicable.


3.3. LABOR EFFORT

Not applicable.

3.4. CREDIT

Not applicable.

First Issue Date			Rev. No.	Revision Date				Page
10	May	2010	---	---	---	---	2-3	

	<p style="text-align: center;">Recommended Service Bulletin No. RSB-AE50R-005</p>	<p>Austro Engine GmbH Rudolf-Diesel-Strasse 11 A-2700 Wiener Neustadt Tel: +43 2622 23000 FAX: +43 2622 23000-2711</p>
---	---	--

4. REMARKS

NOTE:

- All measures must be carried out by a certified engine station and certified engine mechanics.
- The accomplishment of the instructions shown under chapter 2.1 must be confirmed in the respective engine log book.
- The accomplishment of the instructions must be carried out within the time of compliance according chapter 1.4.
- In case of doubt please contact the Austro Engine GmbH – After Sales Support (e-mail: service@austroengine.at; Tel: +43 2622 23000 2525).
- For credit information contact Austro Engine GmbH – After Sales Support (e-mail: service@austroengine.at; Tel: +43 2622 23000 2525)

5. EXPLANATORY NOTES

5.1. SYMBOL EXPLANATION



WARNING: Disregarding these safety rules can cause personal injury or even death



CAUTION: Disregarding these special instructions and safety measures can cause damage to the engine or other components.



NOTE: Additional note or instruction for better understanding of an instruction

6. APPENDIX

None.

First Issue Date			Rev. No.	Revision Date				Page
10	May	2010	---	---	---	---	3-3	