

Airworthiness Directive

1984-10-25

84-180 Schleicher

Date of issue:

October 25, 1984

Affected sailplane:

German Type Certificate No. 339

Schleicher ASK 21

Serial numbers 21194 until 21228.

Subject:

Wheel well

Reason:

Possibly incorrect cut out in the fuselage.

Action and compliance:

Action to be accomplished in accordance with Technical Note immediately after the effective date of this AD.

Technical publication of the manufacturer:

Alexander Schleicher ASK 21 Technical Note No. 17

of October 1, 1984,

which becomes herewith part of this AD and may be obtained from Messrs. Alexander Schleicher, Segelflugzeugbau, D-6416 Poppenhausen, Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by a skilled person and to be checked and entered in the sailplane's log by a licensed inspector.