

Notes:

The structural measures must only be accomplished by the manufacturer Alexander Schleicher or by qualified staff according to applicable law (European Union Commission Regulation (EC) 1321/2014 Part M).


All actions have to be inspected as complex maintenance by certifying staff according to M.A.801 (EC 1321/2014) and have to be certified in the sailplane inspection documents and in the sailplane logbook.

In countries outside the scope of EC 1321/2014 the corresponding national rules shall apply.

Poppenhausen, 07.11.2019

Alexander Schleicher

GmbH & Co.

i.A. 
(P. Anklam)

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10036183.