


|                |   |   |
|----------------|---|---|
| Page<br>1 of 1 | <b>ASK 21</b> Technical Note No. 44<br><b>ASK 21 Mi</b> Technical Note No. 18<br><b>ASK 21 B</b> Technical Note No. 7 | <b>Alexander Schleicher</b><br>GmbH & Co.<br>Segelflugzeugbau<br>D - 36163 Poppenhausen |
|----------------|---|---|

|                               |  |
|-------------------------------|--|
| <b>Subject:</b>               | Towing cable release handle in the front cockpit moved upwards   |
| <b>Applicability:</b>         | <b>ASK 21</b> Type-Certificate EASA.A.221, all serial numbers<br><b>ASK 21 Mi</b> Type-Certificate EASA.A.221, all serial numbers<br><b>ASK 21 B</b> Type-Certificate EASA.A.221, all serial numbers   |
| <b>Classification:</b>        | Minor Change   |
| <b>Urgency:</b>               | Optional for all serial numbers,<br>mandatory for future installations of a hand-operated rudder control, implemented after publishing this Technical Note.  |
| <b>Reason:</b>                | Product improvement  |
| <b>Action:</b>                | <p>The original guidance bracket of the towing cable release handle in the front cockpit is replaced by the new part "Konsole III". The installation is performed according drawing 210.11.9052 „Einbau Konsole III für Kupplungszug vorn, hochgelegt“.</p> <p>For retrofitting, the original bracket has to be removed. In this context, the cables for the towing cable release system from the handles in the rear and front cockpit up to the connection point near the front rudder pedals have to be renewed.</p> <p>This Technical Note replaces the previous variant of relocation of the towing cable release handle according drawing 210.11.S31 (TN 30; point 2 for ASK 21)</p> |
| <b>Material and Drawings:</b> | See Action   |
| <b>Mass and Balance:</b>      | The change in mass and centre of gravity position is negligible.   |
| <b>Notes:</b>                 | The replacement of the bracket and cables of the towing cable release system have to be considered as a complex maintenance task regarding aviation law. The respective national regulations must be applied.  |

Poppenhausen, 16.11.2020

**Alexander Schleicher**  
 GmbH & Co.  
  
 by order  
 (M. Münch)

This Technical Note bases on a change which was approved by EASA under the minor change approval EASA 10075256 dated 18.12.2020.