Page

1 of 1

ASK 21 Mi

Technical Note No. 23 **Alexander Schleicher**

GmbH & Co. Segelflugzeugbau D - 36163 Poppenhausen

Subject: Alternative rotor cooling air intake filter

Applicability: ASK 21 Mi; all serial numbers

Classification: Minor change

Urgency: optional

Reason: The air filter K&N RA 0450 (Austro Engine R1A-06-000-803) installed so far, is no longer

available.

Action: Insert the supplement "LF – New fan air filter", issue 26.06.2023 in chapter 13 of the aircraft

maintenance manual and record the supplement in the list of inserted supplements, section

13.2.

Installing and operating of the alternative air filter according the inserted supplement.

Material and

Drawings: See action

Mass and

Balance: The change in mass and C. of G. position is negligible.

Notes: The actions have to be considered as a non-complex maintenance task regarding aviation

law. The respective regulations must be applied.

Poppenhausen, 07.08.2023

Alexander Schleicher

GmbH & Co.

i.A. P. A. (P. Anklam)

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10082506.