

Subject: Alternative rotor cooling air intake filter

Applicability: **ASH 25 M**; all serial numbers with TN 20 applied ("ASH 25 Mi")

Classification: Minor change

Urgency: optional

Reason: The air filter K&N RA 0450 (Austro Engine R1A-06-000-803) installed so far, is no longer available.

Action: Insert the supplement "LF – New fan air filter", issue 26.06.2023 in chapter 13 of the aircraft maintenance manual and record the supplement in the list of inserted supplements, section 13.2.

Installing and operating of the alternative air filter according the inserted supplement.


Material and Drawings: See action

Mass and Balance: The change in mass and C. of G. position is negligible.

Notes: The actions have to be considered as a non-complex maintenance task regarding aviation law. The respective regulations must be applied.

Poppenhausen, 07.08.2023

Alexander Schleicher
GmbH & Co.

i.A. 
(P. Anklam)

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10082506.