

General maintenance instructions													
----------------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--

---	Wartungsanweisung „Alle GFK-Muster“ (German)	02	02.11.2020	AS 33 Me	all	X								
	Maintenance instruction „All FRP glider models“ (English)					X								
---	Wartungsanweisung über den Einbau von Ausrüstung (German)	02	25.04.2016	AS 33 Me	all	X								
	Maintenance instruction installation of equipment (English)					X								
---	Wartungsanweisung „LACK-RISSE“ (German)	---	26.06.1989	AS 33 Me	all	X								
	Maintenance instruction “PAINT CRACKS” (English)					X								

Doc.-No. 335.99.0001 Issue: 02 Page: 7 of 11	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Me	

Section C: Service bulletins

Doc.-Number	Name	Issue	Date	Applicability												categorisation ¹	manual rev. ²	urgency	Remarks
				Model	Serial No.	EASA													
Type-specific service bulletins																			
AS 33 Me TN No. 1	Alternative Batteriezellen für Antriebsbatterie (German)	---	01.11.2022	AS 33 Me	all	X										O	AFM AMM	none	
	Alternative battery cells for the propulsion battery (English)					X													
AS 33 Me TN No. 2	Ergänzung Wartungshandbuch (German)	---	07.08.2023	AS 33 Me	all	X									M	AFM AMM	31.12.2023		
	Revision of the maintenance manual (English)					X													
335.99.0002	AS 33 Me - TM 3 Gültige Software-Versionen (German)	00	01.11.2023	AS 33 Me	all	X									M	---	none		
	AS 33 Me - TN 3 Approved software versions (English)					X													

¹ M = Mandatory, R = Recommended, O = Optional

² AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No.


335.99.0001

Issue: 02

Page: 8 of 11

List of applicable publications**AS 33 Me****Alexander Schleicher GmbH & Co.
Segelflugzeugbau**Alexander-Schleicher-Straße 1
D-36163 Poppenhausen
(Wasserkuppe)

Doc.- Number	Name	Issue	Date	Applicability												categorisation ¹	manual rev. ²	urgency	Remarks	
				Model	Serial No.	EASA														
General service bulletins																				
TM Nr. 01-2005	Verwendung von Hart-schaumstoff gemäß Werkstoff-Leistungsblatt 5.1460.2 (German)	---	24.02.2005	AS 33 Me	all	X											O	---	none	
TN No. 2-2005	Anerkannte Reparaturverfahren nach EU-VO 1702/2003, Teil 21, Abschnitt M (German)	---	24.05.2005	AS 33 Me	all	X											O	---	none	
	Approved repair procedures according to EU-VO 1702/2003, Part 21, section M (English)					X														
TN No. 02-2008	Anweisung für den Einbau von Ausrüstung (German)	04	21.02.2023	AS 33 Me	all	X											O	---	none	
	Instruction for the installation of equipment (English)					X														
TN No. 02-2013	Verwendung von Pyrofil TR30S- 3K (German)	03	21.02.2023	AS 33 Me	all	X											O	---	none	
	Usage of Pyrofil TR30S-3K (English)					X														
TN No. 01-2020	Ersatz für Polyestervlies PKM 80, Molton oder Flanell 406 (German)	03	21.02.2023	AS 33 Me	all	X											O	---	none	


Doc.-No. 335.99.0001 Issue: 02 Page: 10 of 11	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Me	

Section D: Service information

Doc.-Number	Name	Issue	Date	Applicability												categorisation ³	manual rev. ⁴	urgency	Remarks
				Model	Serial No.	EASA													
99.090.9028	Arbeitsanweisung "Einbau Flarmantenne hinter FW-Klappe" (German)	D	05.01.2023	AS 33 Me	all	X										O	--	none	

³ M = Mandatory, R = Recommended, O = Optional

⁴ AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. 335.99.0001 Issue: 02 Page: 11 of 11	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
AS 33 Me		

Section E: Notes

1. For countries not listed in the tables the owner/operator of the aircraft has to check the applicability of the respective Manual/Service-Bulletin/Service-Info based on the national legal regulations.
2. Mandatory and recommended Service-Bulletins or Service-Information has to be followed by the owner/operator of the aircraft. Non-compliance leads to exclusion of any liability.
3. The applicability of Revisions or Supplements to approved manuals (Flight / Maintenance / Repair) depends on the configuration of the aircraft and has to be checked for each individual serial number.