



Doc.-No.  
**335-99-0001-00**  
 Issue: 03  
 Page: 2 of 11

**List of applicable publications**

---

**AS 33 Me**



**Alexander Schleicher GmbH & Co.**  
**Segelflugzeugbau**

Alexander-Schleicher-Straße 1  
 D-36163 Poppenhausen  
 (Wasserkuppe)

Doc.-Number	Name	Issue	Date	Model	Serial-Numbers	Applicability												Remarks
						EASA	UK											
<b>Supplement to aircraft maintenance manuals</b>																		
---	Ergänzung B – VHF-Antenne im Seitenruder (German)	---	01.11.2022	AS 33 Me	all	X									For aircraft with optional radio antenna in the rudder			
	Supplement B – VHF antenna in the rudder (English)					X	X											
<b>Aircraft repair manuals</b>																		
---	Reparaturhandbuch (German)	---	13.04.1999	AS 33 Me	all	X												
---	Repair manual (English)	---	13.04.1999	AS 33 Me	all	X	X											
<b>Supplement to aircraft repair manuals</b>																		
---	Technische Mitteilung Nr. 01-99 für alle Flugzeugmuster in Faserverbundbauweise (German)	---	12.03.1999	AS 33 Me	all	X												
	Technical note No. 01-99 for all aircraft types of glass fiber & fiber composite construction (English)					X	X											
---	Technische Mitteilung Nr. 03-99 für alle Flugzeugmuster der ASH, ASK & ASW-Baureihen (German)	---	26.03.1999	AS 33 Me	all	X												
	Technical note No. 03-99 for all aircraft of the production series ASH, ASK & ASW (English)					X	X											









Doc.-No. <b>335-99-0001-00</b>  Issue: 03 Page: 7 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 33 Me</b>	

### Section C: Service bulletins

Doc.-Number	Name	Issue	Date	Applicability												categorisation <sup>1</sup>	manual rev. <sup>2</sup>	urgency	Remarks
				Model	Serial No.	EASA	UK												
<b>Type-specific service bulletins</b>																			
AS 33 Me TN No. 1	Alternative Batteriezellen für Antriebsbatterie <a href="#">(German)</a>	---	01.11.2022	AS 33 Me	all	X										O	AFM AMM	none	
	Alternative battery cells for the propulsion battery <a href="#">(English)</a>					X	X												
AS 33 Me TN No. 2	Ergänzung Wartungshandbuch <a href="#">(German)</a>	---	07.08.2023	AS 33 Me	all	X									M	AFM AMM	31.12.2023		
	Revision of the maintenance manual <a href="#">(English)</a>					X	X												
335.99.0002	AS 33 Me - TM 3 Gültige Software-Versionen <a href="#">(German)</a>	00	01.11.2023	AS 33 Me	all	X									M	---	none		
	AS 33 Me - TN 3 Approved software versions <a href="#">(English)</a>					X	X												

<sup>1</sup> M = Mandatory, R = Recommended, O = Optional

<sup>2</sup> AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM







Doc.-No. <b>335-99-0001-00</b>  Issue: 03 Page: 10 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 33 Me</b>	

### Section D: Service information

Doc.-Number	Name	Issue	Date	Applicability												categorisation <sup>3</sup>	manual rev. <sup>4</sup>	urgency	Remarks	
				Model	Serial No.	EASA	UK													
99.090.9028	Arbeitsanweisung "Einbau Flarmantenne hinter FW-Klappe" (German)	D	05.01.2023	AS 33 Me	all	X	X										O	--	none	

<sup>3</sup> M = Mandatory, R = Recommended, O = Optional

<sup>4</sup> AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. <b>335-99-0001-00</b>  Issue: 03 Page: 11 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
<b>AS 33 Me</b>		

## Section E: Notes

1. For countries not listed in the tables the owner/operator of the aircraft has to check the applicability of the respective Manual/Service-Bulletin/Service-Info based on the national legal regulations.
2. Mandatory and recommended Service-Bulletins or Service-Information has to be followed by the owner/operator of the aircraft. Non-compliance leads to exclusion of any liability.
3. The applicability of Revisions or Supplements to approved manuals (Flight / Maintenance / Repair) depends on the configuration of the aircraft and has to be checked for each individual serial number.