













Doc.-No. <b>335-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 7 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 33 Me</b>	

### Section C: Service bulletins

Doc.-Number	Name	Issue	Date	Applicability												categorisation <sup>1</sup>	manual rev. <sup>2</sup>	urgency	Remarks
				Model	Serial No.	EASA	UK	Canada											
<b>Type-specific service bulletins</b>																			
AS 33 Me TN No. 1	Alternative Batteriezellen für Antriebsbatterie <a href="#">(German)</a>	---	01.11.2022	AS 33 Me	all	X											O	AFM AMM	none
	Alternative battery cells for the propulsion battery <a href="#">(English)</a>					X	X	X											
AS 33 Me TN No. 2	Ergänzung Wartungshandbuch <a href="#">(German)</a>	---	07.08.2023	AS 33 Me	all	X										M	AFM AMM	31.12.2023	
	Revision of the maintenance manual <a href="#">(English)</a>					X	X	X											
335.99.0002	AS 33 Me - TM 3 Gültige Software-Versionen <a href="#">(German)</a>	00	01.11.2023	AS 33 Me	all	X										M	---	none	
	AS 33 Me - TN 3 Approved software versions <a href="#">(English)</a>					X	X	X											

<sup>1</sup> M = Mandatory, R = Recommended, O = Optional

<sup>2</sup> AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. <b>335-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 8 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 33 Me</b>	

Doc.-Number	Name	Issue	Date	Model	Serial No.	Applicability										categorisation <sup>1</sup>	manual rev. <sup>2</sup>	urgency	Remarks
						EASA	UK	Canada											
335-99-0003-00	AS 33 Me – TM 4 Sicherung des Triebwerks- instruments <a href="#">(German)</a>	00	21.05.2024	AS 33 Me	all	X										M	AMM	at the next scheduled maintenance action	
	X					X	X												
<b>General service bulletins</b>																			
TM Nr. 01-2005	Verwendung von Hart- schaumstoff gemäß Werk- stoff-Leistungsblatt 5.1460.2 <a href="#">(German)</a>	---	24.02.2005	AS 33 Me	all	X	X	X								O	---	none	
TN No. 2-2005	Anerkannte Reparaturver- fahren nach EU-VO 1702/2003, Teil 21, Ab- schnitt M <a href="#">(German)</a>	---	24.05.2005	AS 33 Me	all	X										O	---	none	
	Approved repair proce- dures according to EU-VO 1702/2003, Part 21, sec- tion M <a href="#">(English)</a>					X	X	X											
TN No. 02-2008	Anweisung für den Einbau von Ausrüstung <a href="#">(German)</a>	04	21.02.2023	AS 33 Me	all	X										O	---	none	
	Instruction for the installa- tion of equipment <a href="#">(English)</a>					X	X	X											
TN No. 02-2013	Verwendung von Pyrofil TR30S- 3K <a href="#">(German)</a>	03	21.02.2023	AS 33 Me	all	X										O	---	none	




Doc.-No.  
**335-99-0001-00**  
 Issue: 05  
 Date: 05.07.2024  
 Page: 9 of 11

**List of applicable publications**

---

**AS 33 Me**



**Alexander Schleicher GmbH & Co.**  
 Segelflugzeugbau

Alexander-Schleicher-Straße 1  
 D-36163 Poppenhausen  
 (Wasserkuppe)

Doc.-Number	Name	Issue	Date	Applicability												categorisation <sup>1</sup>	manual rev. <sup>2</sup>	urgency	Remarks
				Model	Serial No.	EASA	UK	Canada											
	Usage of Pyrofil TR30S-3K <a href="#">(English)</a>					X	X	X											
TN No. 01-2020	Ersatz für Polyestervlies PKM 80, Molton oder Flanell 406 <a href="#">(German)</a>	03	21.02.2023	AS 33 Me	all	X										O	---	none	
	Replacement for polyester fleece PKM 80, Molton or Flanell 406 <a href="#">(English)</a>					X	X	X											
TN No. 02-2020	Einbau AIR Control Display 57 (ACD-57) als primärer Höhenmesser <a href="#">(German)</a>	02	21.02.2023	AS 33 Me	all	X										O	---	none	
	Installation of AIR Control Display 57 (ACD-57) as primary altimeter <a href="#">(English)</a>					X	X	X											

Doc.-No. <b>335-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 10 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 33 Me</b>	

### Section D: Service information

Doc.-Number	Name	Issue	Date	Applicability												categorisation <sup>3</sup>	manual rev. <sup>4</sup>	urgency	Remarks	
				Model	Serial No.	EASA	UK	Canada												
99.090.9028	Arbeitsanweisung "Einbau Flarmantenne hinter FW-Klappe" (German)	D	05.01.2023	AS 33 Me	all	X	X	X									O	--	none	

<sup>3</sup> M = Mandatory, R = Recommended, O = Optional

<sup>4</sup> AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. <b>335-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 11 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 33 Me</b>	

## Section E: Notes

1. For countries not listed in the tables the owner/operator of the aircraft has to check the applicability of the respective Manual/Service-Bulletin/Service-Info based on the national legal regulations.
2. Mandatory and recommended Service-Bulletins or Service-Information has to be followed by the owner/operator of the aircraft. Non-compliance leads to exclusion of any liability.
3. The applicability of Revisions or Supplements to approved manuals (Flight / Maintenance / Repair) depends on the configuration of the aircraft and has to be checked for each individual serial number.

## Section F: Change Record

Issue	Date	Changes
00	29.08.2023	Initial issue
01	29.08.2023	Hyperlinks added
02	02.11.2023	Maintenance instructions 340.99.0002 and 340.99.0003 added; service bulletin 335.99.0002 added
03	06.03.2024	UK added
04	20.06.2024	Canada added
05	05.07.2024	Service bulletin 335-99-0003-00 added