



**Airworthiness
Directive
2000-305**

Luftfahrt-Bundesamt
Airworthiness Directive Section
Hermann-Blenk-Str. 26
38108 Braunschweig
Federal Republic of Germany

Alexander Schleicher

Effective Date: October 05, 2000

Affected:

Kind of aeronautical product: Sailplane
Manufacturer: Alexander Schleicher, Poppenhausen, Germany
Type: ASW 27
Models affected: all
Serial numbers affected: 27001 up to 27104 and 27106 up to 27118
German Type Certificate No.: 389

Subject:

Exchange of pages into the Flight-, Maintenance- and Repair Manual.

Reason:

In case of continuous airworthiness the manufacturer corrected and modified some pages of the Flight-, Maintenance- and Repair Manual.

Action:

Exchange of some pages into the Flight-, Maintenance- and Repair Manual in accordance with the instructions given in the Technical Note of the manufacturer (action „B“ of the Technical Note).

Compliance:

The exchange of the Aircraft Documents must be done before the next annual inspection, but not later than December 31, 2000.

Technical publication of the manufacturer:

Alexander Schleicher ASW 27 Technical Note No. 6 dated May 16, 2000 which becomes herewith part of this AD and may be obtained from Messrs.:

Alexander Schleicher
GmbH & Co.
Segelflugzeugbau

D- 36163 Poppenhausen
Federal Republic of Germany
Phone: ++ 49 6658 89-0, Fax: ++ 49 6658 89-40
Mail: sales@alexander-schleicher.de

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.

Holders of affected aircraft registered in Germany have to observe the following:

As a result of the a.m. deficiencies, the airworthiness of the aircraft is affected to such an extent that after the expiry of the a.m. dates the aircraft may be operated only after proper accomplishment of the prescribed actions. In the interest of aviation safety outweighing the interest of the receiver in a postponement of the prescribed actions, the immediate compliance with this AD is to be directed

Instructions about Available Legal Remedies:

An appeal to this notice may be raised within a period of one month following notification. Appeals must be submitted in writing or registered at the Luftfahrt-Bundesamt, Hermann-Blenk-Str. 26, 38108 Braunschweig.

Enquiries regarding this Airworthiness Directive should be referred to Mr.Olaf Schneider, Airworthiness Directive Section at the above address, fax-no. 0049 531/2355-720. Please note, that in case of any difficulty, reference should be made to the German issue!