Cockpit vent behind the canopy frame

1 General

Behind the canopy an opening for the ventilation of the cockpit was installed

2 Limitations

No changes become necessary for Limitations

3 Emergency Procedures

No changes become necessary for Emergency Procedures.

4 Normal Procedures

CAUTION: Unconditionally avoid flying through rain, because water could ingress.

When parking the glider outdoors, the opening has to be taped water-tight.

Though, if the glider was nevertheless subjected to rain with open vent, or was flown through rain, the seat pan has to be removed, everything has to be dried up, and – if applicable - the parachute has to be inspected.

5. Performance

No changes become necessary for Performance

6 Weight and Balance

No changes become necessary for Weight and Balance