Cockpit vent behind the canopy frame

1 General

Behind the canopy an opening for the ventilation of the cockpit was installed

2 Limitations

No changes become necessary for Limitations

3 Emergency Procedures

No changes become necessary for Emergency Procedures.

4 Normal Procedures

CAUTION: Unconditionally avoid flying through rain, because water could ingress.

When parking the glider outdoors, the opening has to be taped watertight.

Though, if the glider was nevertheless subjected to rain with open vent, or was flown through rain, the seat pan has to be removed, everything has to be dried up, and – if applicable - the parachute has to be inspected.

5. Performance

No changes become necessary for Performance

6 Weight and Balance

No changes become necessary for Weight and Balance

Issue: TN 7 / 01.03.11

Revision: