

Additional support of the elevator push rod at bulkhead 20.

Urgency: All new gliders. It is recommended to be made on the other gliders at general overhauls.

- 1) After modified drawing L - 205 - 10 - S 9 to be made at all new gliders.
- 2) Allready made from serial number 1127 of Schleicher } production.
11 of Siebert }
- 3) At former S. Nb. it is recommended to make the modification at repairs or overhauls.
- 4) Parts are to be ordered from the Fa. Schleicher.

Approval of translation has been done by best knowledge and judgement. - In any case the original text in German language is authoritative.

Drawings and lists
to be corrected:

Notice: Made from
S. Nb. 1127/11

PfL-Prüfvermerk

Drwawing L - 205.10 -
S 9

ausgef. 24.10.61. Kaiser
geprüft



Reinher
28. Nov. 1963