

Sheet 1

Nb. of Sheets 2

Modification Nr. 2
Powered glider ASK 14
L - 684

Alexander Schleicher
Segelflugzeugbau
6416 Poppenhausen

Reason: Installation of a collar around the filler inlet of the fuel tank to prevent pouring fuel into the luggage compartment. Plotting of some fuel metering marks on the tank front side.

Description of modification: All new aircraft are to be modified after drawing on sheet 2.

Drawings to be corrected	Remarks	
	17.3.1970 <i>Keine</i>	
	Modification to be made at all new aircraft.	