

Sheet 1
Number of sheets: 1

ASW 15
Technical Note
No. 1

Alexander Schleicher
Segelflugzeugbau
6416 Poppenhausen

Subject: Horn mass balance of the rudder.

Effectivity: ASW 15, serial numbers 15003 and 15005.

Accomplishment: Immediately.

Reason: During the testflights of the serial models oscillations of the tailplane have been noticed.

Instructions: According to drawing No. 150 36/7 Bl. 17, the new mass balance horn must be installed.
The old mass balance between the hinges on the rudder nose must be removed.

Material: A set of parts for modification No. 1 must be ordered at the Schleicher Sailplanes Firm.

Weight and Balance: The Center of Gravity must be tested with the modification.

Remarks: The modification is not essential on 15002 and is already made on all ASW 15 except 15003 and 15005.

Drawings: Drawing No. 150 36/7, Bl. 17.

Poppenhausen, the 6th of March 1970.

ALEXANDER SCHLEICHER
Segelflugzeugbau

G. Waibel

German Original approved by
Luftfahrt-Bundesamt, Braunschweig,
(Federal Office of Civil Aeronautics of the
Federal Republic of Germany)