Subject : Installation of a cabin heater

Effectivity: Powered glider ASK 16 L - 758,

all Serial Numbers

Accomplishment : It is already installed in Serial Number 16 014

and from Serial Number 16 019 on.

For all other Serial Numbers installation is

optional.

Instruction : The installation has to be made according to the

dravings

L - 758, 61 - HZ 1

L - 758, 61 - HZ 2

L - 758, 61 - HZ 3

L - 758. 61 - HZ 4

and part list 65/78/1

To be changed at the Flight Manual :

Sheet 9 to HZ 9,

and at the Maintenance Manual :

Sheet 4 to HZ 4.

Material : See notes at the drawings

Weight : To be neglected

Balance : To be neglected

Remarks : The modification has to be made by the manufac-

turer ( Schleicher Company ) or an approved

airframe repair shop.

Parts are to be ordered at Schleicher Company.

The heat exchanger must not be used with the old

exhaust muffler according to drawing

L - 758, 61 - 89

Peppenhausen, 8th July, 1974

ALEXANDER SCHLEICHER Segelflugseugbau

miney triz