

AIRWORTHINESS DIRECTIVE

91-148 Schleicher

Date of issue:

2. SEP. 1991

Affected sailplane:

German Type Certificate No. 351

ASW 22

Serial no.s: 22001 thru 22022

22024 thru 22027

22029 thru 22033

22035 thru 22037

22039 and 22046

Subject:

Inspecting the elevator engaging (on the top of the fin) in accordance with the instructions given in the Flight and Maintenance Manuals.

Action and compliance:

Action to be accomplished in accordance with ASW 22 Technical Note No. 7 during next annual CofA inspection, but before or on January 1, 1992, at the latest. Where a glider has had rather long transports in its trailer, the action must be done prior to the next take-off. Thereafter during each annual CofA inspection.

Technical publication of the manufacturer:

Schleicher ASW 22 Technical Note No. 7 of June 28, 1991, which becomes herewith part of this AD and may be obtained from Messrs.

Alexander Schleicher  
GmbH & Co.  
Segelflugzeugbau  
D-6416 Poppenhausen  
Federal Republic of Germany

Accomplishment and log book entry:

Action to be accomplished by a skilled person or an approved service station and to be checked and entered in the sailplane's log by a licensed inspector.