Subject:       Blow holes, NACA inlets and Zig-Zag Tape: Drawing revision Maintenance Instruction A Issue II 16.03.2015         Applicability:       ASH 31 Mi, Type-Certificate EASA A.538         Classification:       Minor Change         Urgency:       Optional         Reason:       Correction on drawings, changing of position of zig-zag tape. This changes will be used in the Maintenance Instruction A of the ASH 31 Mi.         Action:       The previous drawing 310.51.9018 "Position Ausblasung, NACA-Hutzen und Zacken- bander" will be corrected. The new drawing 310.51.9020 shows a new combination of zig-zag tape and blow holes.         Exchange page 13.4 of the Maintenance Manual, Revision TN 07 dated 16.03.2015.         Replace Maintenance Instruction A with Issue 2 dated 16.03.2015.         Material and Drawings:       see Action         Mass and Balance:       A new weighing is not necessary.         Notes:       Al actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the solpada and in the saliplane ing drawing be entered in the "Record of Revisions" page and in the _List of effective pag- es".         Poppenhausen, 16.03.2015       Alexander Schleicher GmbH & Co. by order         Papie.       Minoch)         This change was approved by the EASA on 27.05.2015 with the Minor Change Approval 10053432.	Page 1 of 1		<b>ASH 31 Mi</b> Technical Note No. 7	Alexander Schleicher GmbH & Co. Segelflugzeugbau D - 36163 Poppenhausen	
Classification:       Minor Change         Urgency:       Optional         Reason:       Correction on drawings, changing of position of zig-zag tape. This changes will be used in the Maintenance Instruction A of the ASH 31 Mi.         Action:       The previous drawing 310.51.9018 "Position Ausblasung, NACA-Hutzen und Zackenbänder" will be corrected. The new drawing 310.51.9020 shows a new combination of Zig-zag tape and blow holes.         Exchange page 13.4 of the Maintenance Manual, Revision TN 07 dated 16.03.2015.         Replace Maintenance Instruction A with Issue 2 dated 16.03.2015.         Material and Drawings:       see Action         Mass and Blance:       A new weighing is not necessary.         Notes:       All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the saliplane inspection documents and in the saliplane logbook. The manual page changes can be carried out by the operator of the saliplane and must be entered in the "Record of Revisions" page and in the _List of effective pagers".         Poppenhausen; 18.03.2015       Lacander Schleicher         Serverties       Simble & Co.         Warder       Muinch	Subject:				
Urgency:       Optional         Reason:       Correction on drawings, changing of position of zig-zag tape. This changes will be used in the Maintenance Instruction A of the ASH 31 Mi.         Action:       The previous drawing 310.51.9018 "Position Ausblasung, NACA-Hutzen und Zackenbänder" will be corrected. The new drawing 310.51.9020 shows a new combination of zig-zag tape and blow holes.         Exchange page 13.4 of the Maintenance Manual, Revision TN 07 dated 16.03.2015.       Replace Maintenance Instruction A with Issue 2 dated 16.03.2015.         Material and Drawings:       see Action         Mass and Balance:       A new weighing is not necessary.         Notes:       All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the saliplane inspection documents and in the saliplane and must be entered in the .Record of Revisions" page and in the .List of effective pages".         Poppenhausen, 16.03.2015       Alexander Schleicher         Poppenhausen, 16.03.2015       Alexander Schleicher         GmbH & Co.       by order         May       GmbH & Co.         Worder       M. Münch)	Applicability:	ASH 31 Mi, Type-Certificate EASA.A.538			
Reason:       Correction on drawings, changing of position of zig-zag tape. This changes will be used in the Maintenance Instruction A of the ASH 31 Mi.         Action:       The previous drawing 310.51.9018 "Position Ausblasung, NACA-Hutzen und Zackenbänder" will be corrected. The new drawing 310.51.9020 shows a new combination of zig-zag tape and blow holes.         Exchange page 13.4 of the Maintenance Manual, Revision TN 07 dated 16.03.2015.       Replace Maintenance Instruction A with Issue 2 dated 16.03.2015.         Material and Drawings:       see Action         Mass and Balance:       A new weighing is not necessary.         Notes:       All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the sailplane inspection documents and in the sailplane and must be entered in the "Record of Revisions" page and in the "List of effective pages".         In countries outside the scope of EC 2042/2003 the corresponding national rules shall apply.         Poppenhausen, 16.03.2015         Alexander Schleicher         GmbH & Co.         by order         Muterial         Motes:       CombH & Co.         Material and Drawing Science       Minethenance         Material and Drawings:       See Action         Mass and Balance:       A new weighing is not necessary.         Notes:       All actions are to be inspected by certifying individua	Classification:	Minor Change			
<ul> <li>in the Maintenance Instruction A of the ASH 31 Mi.</li> <li>Action: The previous drawing 310.51.9018 "Position Ausblasung, NACA-Hutzen und Zackenbänder" will be corrected. The new drawing 310.51.9020 shows a new combination of zig-zag tape and blow holes.</li> <li>Exchange page 13.4 of the Maintenance Manual, Revision TN 07 dated 16.03.2015.</li> <li>Replace Maintenance Instruction A with Issue 2 dated 16.03.2015.</li> <li>Material and Drawings: see Action</li> <li>Mass and Balance: A new weighing is not necessary.</li> <li>Notes: All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the sailplane inspection documents and in the sailplane and must be entered in the "Record of Revisions" page and in the "List of effective pages".</li> <li>In countries outside the scope of EC 2042/2003 the corresponding national rules shall apply.</li> </ul>	Urgency:	Optional			
<ul> <li>bänder" will be corrected. The new drawing 310.51.9020 shows a new combination of zig-zag tape and blow holes.</li> <li>Exchange page 13.4 of the Maintenance Manual, Revision TN 07 dated 16.03.2015.</li> <li>Replace Maintenance Instruction A with Issue 2 dated 16.03.2015.</li> <li>Material and Drawings: see Action</li> <li>Mass and Balance: A new weighing is not necessary.</li> <li>Notes: All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the saliplane inspection documents and in the saliplane logbook. The manual page changes can be carried out by the operator of the saliplane inspection documents and in the saliplane and must be entered in the "Record of Revisions" page and in the "List of effective pages".</li> <li>In countries outside the scope of EC 2042/2003 the corresponding national rules shall apply.</li> </ul>	Reason:				
Replace Maintenance Instruction A with Issue 2 dated 16.03.2015.         Material and Drawings:       see Action         Mass and Balance:       A new weighing is not necessary.         Notes:       All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the sailplane inspection documents and in the sailplane and must be entered in the "Record of Revisions" page and in the "List of effective pages".         Poppenhausen, 16.03.2015       Alexander Schleicher         GmbH & Co.       by order         Mass And Die Construction Action Ac	Action:	bände	bänder" will be corrected. The new drawing 310.51.9020 shows a new combination of		
Material and Drawings:       see Action         Mass and Balance:       A new weighing is not necessary.         Notes:       All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the saliplane inspection documents and in the saliplane logbook. The manual page changes can be carried out by the operator of the saliplane and must be entered in the "Record of Revisions" page and in the "List of effective page es".         In countries outside the scope of EC 2042/2003 the corresponding national rules shall apply.         Poppenhausen, 16.03.2015         Alexander Schleicher         GmbH & Co.         by order         Material and Draw and must be and the scope of EC 2042/2003 the corresponding national rules shall apply.         Poppenhausen, 16.03.2015		Excha	xchange page 13.4 of the Maintenance Manual, Revision TN 07 dated 16.03.2015.		
Drawings:       see Action         Mass and Balance:       A new weighing is not necessary.         Notes:       All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the saliplane inspection documents and in the saliplane logbook. The manual page changes can be carried out by the operator of the saliplane logbook. The manual page changes can be carried out by the operator of the saliplane and must be entered in the "Record of Revisions" page and in the "List of effective pages".         Poppenhausen, 16.03.2015       Alexander Schleicher         GmbH & Co.       by order         GmbH & Co.       by order         Mass and must be entered in the manual page for the saliplane inspection documents and in the saliplane logbook. The manual page changes can be carried out by the operator of the saliplane and must be entered in the "Record of Revisions" page and in the "List of effective pages".         In countries outside the scope of EC 2042/2003 the corresponding national rules shall apply.         Poppenhausen, 16.03.2015       Alexander Schleicher         GmbH & Co.       by order         Mass.       Mass.         Mass.       Mass.         Mass.       Mass.		Replac	Replace Maintenance Instruction A with Issue 2 dated 16.03.2015.		
Balance:       A new weighing is not necessary.         Notes:       All actions are to be inspected by certifying individuals according to European Union Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modification and have to be certified in the sailplane inspection documents and in the sailplane logbook. The manual page changes can be carried out by the operator of the sailplane and must be entered in the "Record of Revisions" page and in the "List of effective pages".         In countries outside the scope of EC 2042/2003 the corresponding national rules shall apply.         Poppenhausen, 16.03.2015         Alexander Schleicher         GmbH & Co.         by order       J		see Action			
Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modifica- tion and have to be certified in the sailplane inspection documents and in the sailplane logbook. The manual page changes can be carried out by the operator of the sailplane and must be entered in the "Record of Revisions" page and in the "List of effective pag- es". In countries outside the scope of EC 2042/2003 the corresponding national rules shall apply. Poppenhausen, 16.03.2015 Alexander Schleicher GmbH & Co. by order M. Münch)		A new weighing is not necessary.			
apply. Poppenhausen, 16.03.2015 Alexander Schleicher GmbH & Co. by order (M. Münch)	Notes:	Comm tion ar logboo and m	Commission Regulation (EC) 2042/2003 Part M / Part 66 within the scope of a modifica- tion and have to be certified in the sailplane inspection documents and in the sailplane logbook. The manual page changes can be carried out by the operator of the sailplane and must be entered in the "Record of Revisions" page and in the "List of effective pag-		
Alexander Schleicher GmbH & Co. by order (M. Münch)					
GmbH & Co. by order (M. Münch)					
by order (M. Münch)					
This change was approved by the EASA on 27.05.2015 with the Minor Change Approval 10053432.					
	This change was a	approved	by the EASA on 27.05.2015 with the Minor Change A	Approval 10053432.	