

Table of AD-Notes and Technical Notes

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau
D-36163 PoppenhausenType: **ASH 31 Mi**Data Sheet No.: **EASA.A.538**Sheet: **1 of 1**License: **DE.21G.0010**

TN-No	LBA-AD-No. Issue Date	TN Issue Date	Version & Serial No. affected	Subject	Compliance	Inspection Ref.
				intentionally left blank		
2	--	10.04.14 EASA-app.: 26.03.14	ASH 31 Mi all serial numbers	Exchange of the steerable tailwheel	none, optional mod on customer's request	
3	--	19.09.14 EASA-app.: 19.09.14	ASH 31 Mi all serial numbers	Trouble shooting of the Engine Control Unit (ECU)	see Austro Engine Mandatory Service Bulletin No. MSB-AE50R-006	10050545
4	--	16.03.15 EASA-app.: 27.05.15	ASH 31 Mi all serial numbers	Installation of the smaller version of the ILEC Instrument (Control Unit)	none, optional mod on customer's request	10053432
5	--	20.05.15 EASA-app.: 07.05.15	ASH 31 Mi all serial numbers	New calibration of the rotor internal cooling temperature depending on the position of the temperature sensor.	none, optional mod on customer's request	10053240
6	--	16.03.15 EASA-app.: 27.05.15	ASH 31 Mi all serial numbers	Automatic fuel filling shut-off system	none, optional mod on customer's request	10053432
7	--	16.03.15 EASA-app.: 27.05.15	ASH 31 Mi all serial numbers	Blow holes, NACA inlets and Zig-Zag-Tape: Drawing rev., Maintenance Instruction A Issue II 16.03.2015	none, optional mod on customer's request	10053432
8	--	26.09.16 EASA-app.: 07.09.16	ASH 31 Mi all serial numbers with shock absorbing strut II	Self-loosening of a bolted assembly inside the shock absorbing struts of the main landing gear.	Check at the next airworthiness review, implementation not later than 31.12.2017	10059305
9	--	26.09.16 EASA-app.: 07.09.16	ASH 31 Mi all serial numbers equipped with the small ILEC from new or by TN 04	Calibrating the fuel contents with the small ILEC Engine Control Unit according to TN 04 is generating an error message.	none, only in case of problems with the recalibration of the fuel level, which can occur when changing to a different, permitted fuel grade. Standard since 26.09.2016.	10059305