

Summary of Airworthiness Directives (AD) and Technical Notes (TN)

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau
D-36163 Poppenhausen

Type: **ASK 18**

Data Sheet No.: **307**

Sheet: **1 of 2**

License: **DE.21G.0010**

TN-No.	AD-No. Date of Issue	TN Date of Issue	Affected Production Series and Serial No.'s	Subject	Compliance	Inspector's stamp
1		09.09.75 LBA-appr.:22.09.75	ASK 18 all serial numbers from S/N 18010 serial standard	Installation of mass balance to aileron	change before 01.06.1976	
2		16.03.76 LBA-appr.:30.04.76	all ASK 18	Installation of a nose hook	installation is optional	
3		26.04.76 LBA-appr.:03.06.76	all ASK 18	Enlarging of the center of gravity margin	--	
4		01.07.76 LBA-appr.:05.01.77	all ASK 18	Modification to version ASK 18 B (shortening the span to 15 m)	optional when needed	
5		17.08.76 LBA-appr.:27.09.76	all ASK 18	Exchange of material	--	
--	82-216 09.11.82	without	all model variants	Speezed "Nico-press" sleeves	action to be accomplished until the next annual C. of A. inspection, but before or on 31.01.1983 , at the latest	
6	72-7/3 17.10.89	04.10.89 LBA-appr.:17.10.89	all ASK 18 and ASK 18 B all serial numbers	Loose glue joints on rib 1 of the elevator	Before the next start The above action under points 1. and 2. must be repeated every three years during the annual re- inspection	
7		17.01.90 LBA-appr.:01.03.90	all ASK 18 and ASK 18 B	New production series tow release couplings for aerotow and winch launch	applicable to new built gliders and in case of replacement of tow release couplings	
8		13.04.10 EASA-app.: 17.05.10	all ASK 18 all model variants	Inspection of the central support of the elevator	before the next annual inspection	

Summary of Airworthiness Directives (AD) and Technical Notes (TN)

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau
D-36163 Poppenhausen

Type: **ASK 18**

Data Sheet No.: **307**

Sheet: **2 of 2**

License: **DE.21G.0010**

TN-No.	AD-No. Date of Issue	TN Date of Issue	Affected Production Series and Serial No.'s	Subject	Compliance	Inspector's stamp
9	AD 2013-0991 12.04.13	08.01.13 Rev. 1 EASA-gen.: 03.09.12	all ASK 18 all model variants	Inspection of the automatic elevator control connection	before the next annual inspection	10041262
10	AD 2021-0230 14.10.21	12.07.21 EASA-app.: 08.07.21	all ASK 18 all model variants	Inspection of the elevator	Action A: within 30 days Action B: until 31.12.2021 by the latest	
11		12.07.21 EASA-app.: 08.07.21	all ASK 18 all model variants	Limitation of the operating range	optional / strongly recommended	