

**Subject:** Revision of the maintenance manual  
**Applicability:** **ASK 21 B**; Type Certificate EASA.A.221; all serial numbers  
**Urgency:** mandatory, 31.12.2023  
**Reason:** Improvement of documentation  
**Action:** The following pages of the manuals have to be exchanged:

Maintenance Manual German: 2.22, 13.4  
Maintenance Manual English: 2.22, 13.4

The new manual pages are marked with the technical note number TN 10 from 11.04.2023 as revision.

The exchange of the pages has to be noted in the record of revision of the manual. The list of effective pages must be updated, too.

**Material and Drawings:** see action

**Mass and Balance:** No change on the mass and C. of G. position.

**Notes:** The revision of the maintenance manual has to be considered as a pilot-owner maintenance task regarding aviation law. The respective regulations must be applied.

Poppenhausen, 07.08.2023

**Alexander Schleicher**  
GmbH & Co.

i.A.   
(T. Mörsel)

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10082506.