

Subject: Revision of the maintenance manual

Applicability: **ASW 28 B**; Type-Certificate EASA.A.017

Urgency: mandatory, 31.12.2023

Reason: Improvement of documentation

Action: The following pages of the manuals have to be exchanged:

Maintenance Manual German: 2.12, 2.31, 10.8
Maintenance Manual English: 2.12, 2.31, 10.8

The new manual pages are marked with the technical note number TN 1 from 11.04.2023 as revision.
The exchange of the pages has to be noted in the record of revision of the manual. The list of effective pages must be updated, too.

Material and Drawings: see action

Mass and Balance: No change on the mass and C. of G. position.

Notes: The revision of the maintenance manual has to be considered as a pilot-owner maintenance task regarding aviation law. The respective regulations must be applied.

Poppenhausen, 07.08.2023

Alexander Schleicher
GmbH & Co.

i.A. 
(T. Mörsel)

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10082506.