

Subject: Revision of the maintenance manual

Applicability: **ASG 32**; Type-Certificate EASA.A.599; all models; all serial numbers

Urgency: mandatory, 31.12.2023

Reason: Improvement of documentation

Action: ASG 32 Mi
The following pages of the manuals have to be exchanged by new manual pages that are marked with the technical note number TN 4 / TN 14 from 11.04.2023 as revision:
Maintenance Manual German (issue 15.01.2016): 2.67, 13.4
Maintenance Manual English (issue 15.01.2016): 2.67, 13.4

ASG 32 EI
The following pages of the manuals have to be exchanged by new manual pages that are marked with the technical note number TN 14 from 11.04.2023 as revision:
Maintenance Manual German (issue 01.04.2017): 2.62, 13.4
Maintenance Manual English (issue 01.04.2017): 2.62, 13.4

ASG 32
The following pages of the manuals have to be exchanged by new manual pages that are marked with the technical note number TN 4 / TN 14 from 11.04.2023 as revision:
Maintenance Manual German (issue 15.01.2016): 2.44, 13.4
Maintenance Manual English (issue 15.01.2016): 2.44, 13.4

The exchange of the pages has to be noted in the record of revision of the manual. The list of effective pages must be updated, too.

Material and Drawings: see action

Mass and Balance: No change on the mass and C. of G. position.

Notes: The revision of the maintenance manual has to be considered as a pilot-owner maintenance task regarding aviation law. The respective regulations must be applied.

Poppenhausen, 07.08.2023

Alexander Schleicher
GmbH & Co.

i.A. 
(T. Mörsel)

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10082506.