



Doc.-No. 336.99.0001 Issue: 01 Page: 1 of 12	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Section A: Manuals

Doc.-Number	Name	Issue	Date	Model	Serial-Numbers	Applicability										Remarks	
						EASA	UK	Australia	New Zealand								
Aircraft flight manuals																	
---	Flughandbuch für das nicht eigenstartfähige Segelflugzeug AS 33 Es (German)	---	25.08.2020	AS 33 Es	33001 – 33009 & 33015	X	-	-	-								Only applicable unless TN 01 is performed
---	Flight manual for the self-sustaining powered sailplane AS 33 Es (English)	---	25.08.2020	AS 33 Es	33001 – 33009 & 33015	X	X	-	-								
---	Flughandbuch für das nicht eigenstartfähige Segelflugzeug AS 33 Es (German)	---	01.11.2020	AS 33 Es	all	X	-	-	-								
---	Flight manual for the self-sustaining powered sailplane AS 33 Es (English)	---	01.11.2020	AS 33 Es	all	X	X	X	X								
Supplements to aircraft flight manual																	
---	Ergänzung B – Batterie in der Rumpfröhre (German)	---	28.04.2021	AS 33 Es	all	X	-	-	-								For aircraft with optional battery in the fuselage tail cone
	Supplement B – Battery in fuselage tail cone (English)					X	X	X	X								

Doc.-No. 336.99.0001	List of applicable publications					Alexander Schleicher GmbH & Co. Segelflugzeugbau	
	Issue: 01 Page: 2 of 12	AS 33 Es				Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)	

Doc.-Number	Name	Issue	Date	Model	Serial-Numbers	Applicability										Remarks	
						EASA	UK	Australia	New Zealand								
Aircraft maintenance manuals																	
---	Wartungshandbuch für das nicht eigenstartfähige Segelflugzeug AS 33 Es (German)	---	25.08.2020	AS 33 Es	33001 – 33009 & 33015	X	-	-	-								Only applicable unless TN 01 is performed
---	Maintenance manual for the self-sustaining powered sailplane AS 33 Es (English)	---	25.08.2020	AS 33 Es	33001 – 33009 & 33015	X	X	-	-								
---	Wartungshandbuch für das nicht eigenstartfähige Segelflugzeug AS 33 Es (German)	---	01.11.2020	AS 33 Es	all	X	-	-	-								
---	Maintenance manual for the self-sustaining powered sailplane AS 33 Es (English)	---	01.11.2020	AS 33 Es	all	X	X	X	X								
Supplement to aircraft maintenance manuals																	
---	Ergänzung A – VHF-Antenne im Seitenruder (German)	---	19.03.2021	AS 33 Es	all	X	-	-	-								For aircraft with optional radio antenna in the rudder
	Supplement A – VHF antenna in the rudder (English)					X	X	X	X								
---	Ergänzung B – Batterie in der Rumpfröhre (German)	---	28.04.2021	AS 33 Es	all	X	-	-	-								For aircraft with optional battery in the fuselage tail cone
	Supplement B – Battery in fuselage tail cone (English)					X	X	X	X								

Doc.-No. 336.99.0001 Issue: 01 Page: 8 of 12	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Section C: Service bulletins

Doc.-Number	Name	Issue	Date	Model	Serial No.	Applicability										categorisation ¹	manual rev. ²	urgency	Remarks	
						EASA	UK	Australia	New Zealand											
Type-specific service bulletins																				
AS 33 Es TN No. 1	Erweiterung Flugbereich (German)	---	09.03.2021	AS 33 Es	33001 - 33009 & 33015	X	-	-	-								M	AFM AMM	31.12.2021	
	Expansion of flight-envelope (English)					X	X	X	X											
AS 33 Es TN No. 2	Einbau Tankerweiterung Kraftstoffsystem (German)	---	09.03.2021	AS 33 Es	all	X	-	-	-							O	---	none		
	Installation of a fuel tank extension (English)					X	X	X	X											
AS 33 Es TN No. 3	Batteriehalterung Ausführung 2 im Gepäckraum (German)	---	28.04.2021	AS 33 Es	all	X	-	-	-							O	AFM	none		
	Battery holder version 2 in the baggage compartment (English)					X	X	X	X											
AS 33 Es TN No. 4	15m Außenflügel (German)	02	03.01.2022	AS 33 Es	all	X	-	-	-							O	AFM AMM	none		
	15m outer wings (English)					X	X	X	X											
AS 33 Es TN No. 5	Flügelrädchen (German)	---	08.03.2023	AS 33 Es	all	X	-	-	-							O	---	non		
	Wing tip wheels (English)					X	X	X	X											

¹ M = Mandatory, R = Recommended, O = Optional

² AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No.


336.99.0001

Issue: 01

Page: 9 of 12

List of applicable publications**AS 33 Es****Alexander Schleicher GmbH & Co.
Segelflugzeugbau**Alexander-Schleicher-Straße 1
D-36163 Poppenhausen
(Wasserkuppe)

Doc.- Number	Name	Issue	Date	Model	Serial No.	Applicability										categorisation ¹	manual rev. ²	urgency	Remarks	
						EASA	UK	Australia	New Zealand											
AS 33 Es TN No. 6	Gelenkköpfe Quersteuerung (German)	02	08.03.2023	AS 33 Es	33003 - 33051	X	-	-	-								R	---	31.03.2023	
	Push rod end bearings ai- leron control (English)					X	X	X	X											
AS 33 Es TN No. 7	Schwerpunktkupplung (German)	---	22.03.2023	AS 33 Es	all	X	-	-	-							O	AMM -Sup	none		
	C.G.-hook (English)					X	X	X	X											
AS 33 Es TN No. 8	Ergänzung Wartungs- handbuch (German)	---	07.08.2023	AS 33 Es	all	X	-	-	-							M	AMM	31.12.2023		
	Revision of the maintenance manual (English)					X	X	X	X											
General service bulletins																				
TM Nr. 01-2005	Verwendung von Hart- schaumstoff gemäß Werk- stoff-Leistungsblatt 5.1460.2 (German)	---	24.02.2005	AS 33 Es	all	X	X	X	X								O	---	none	
TN No. 02-2005	Anerkannte Reparaturverfah- ren nach EU-VO 1702/2003, Teil 21, Abschnitt M (German)	---	24.05.2005	AS 33 Es	all	X	-	-	-							O	---	none		
	Approved repair procedures according to EU-VO 1702/2003, Part 21, sec- tion M (English)					X	X	X	X											

Doc.-No. 336.99.0001 Issue: 01 Page: 11 of 12	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Section D: Service Information

Doc.- Number	Name	Issue	Date	Applicability												categorisation ³	manual rev. ⁴	urgency	Remarks	
				Model	Serial No.	EASA	UK	Australia	New Zealand											
99.090.9028	Arbeitsanweisung "Einbau Flarmantenne hinter FW-Klappe" (German)	D	05.01.2023	AS 33 Es	all	X	X	X	X								O	--	none	

³ M = Mandatory, R = Recommended, O = Optional

⁴ AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. 336.99.0001 Issue: 01 Page: 12 of 12	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Section E: Notes

1. For countries not listed in the tables the owner/operator of the aircraft has to check the applicability of the respective Manual/Service-Bulletin/Service-Info based on the national legal regulations.
2. Mandatory and recommended Service-Bulletins or Service-Information has to be followed by the owner/operator of the aircraft. Non-compliance leads to exclusion of any liability.
3. The applicability of Revisions or Supplements to approved manuals (Flight / Maintenance / Repair) depends on the configuration of the aircraft and has to be checked for each individual serial number.